



## Back-to-back 'Z' Purlins



Purlin assemblies to be attached to end plates in field.

## SIDE VIEW



*Note: It is important NEVER to walk on top of a Bally ceiling that is not supported by interior steel or other temporary structural supports. Failure to support ceiling will cause joint failure and likely cause serious injury or death.*